



## Security Advisory

CVE -2019-10126

Marvell was made aware of a potential vulnerability (CVE -2019-10126) that was found in the 88W8887 Open Source Linux driver. The heap-based buffer overflow in `mwifiex_uap_parse_tail_ies` function in open source driver is believed to lead to memory corruption. The potential vulnerability also exists in the proprietary Linux driver.

While there is low probability of exploitation on the affected systems, Marvell places the highest priority on addressing security concerns and has deployed a fix to address this issue. We have been working closely with our customers to update Marvell's latest firmware and driver to implement the most recent security enhancements.

Marvell encourages customers to contact their Marvell representative for additional support.